

EXHIBIT U



Pole Detail Report



Location Information

Equip ID:	102292423	Pole Num:		Map Lat:	38.409797
Map Name:	JJ39	Structure:		Map Lng:	-122.246232
Owner:	PG&E owned pole			Show in Map Guide	
Address:	3683 ATLAS PEAK RD 10S			Show in Google Map	
Cust Info:	VISUAL				
Access:	Readily Accessible			Environmental:	No environmental conditions
Reason:	No Access Issues			Alerts:	No Alerts

Immediate Response Conditions:	Immediate Response Comments:
No Immediate Response Conditions	

GIS Guid:	19925E15D9304A69A819A2D8E19CDBC8
-----------	----------------------------------

Pole Asset Information

Pole Type:	Wood	Location:	Private property	Attachments:	Communications, Distribution
Surface:	Dirt	Walkway:	0	JP Num:	PT6543
Supplier:	Koppers Co	Mfr Year:	1980	Ins Year:	1980
Species:	Douglas Fir	Class:	5	Height:	40
Orig Treat:	Cellon Gas	Orig Circ:	33	Estimated Data:	<input type="checkbox"/>
Existing Rnfcmnt:	No Reinforcement	Solid Surface:	<input type="checkbox"/>		

Inspection History

SIL_C9_041	1 of 3
------------	--------

Project Status:	ACTIVE	Contractor:	OSM		
Foreman:	m4a0	Current Circ:	33.00	Snow Load:	
Pole Work Status:	Complete	Effective Circ:	33.00	Front Span Length:	
Crew ID:	OSM241	Encl Pkt Count:		Back Span Length:	
Visit Date:	10/26/2017	Exp Pkt Count:		Full Span Count:	
Work Report:		Mch Dmg Count:		Single Span Count:	
Insptn Type:	Test and Treat	Steel Installed:		Equip Count:	
Excavation:	No Excavation	No Steel Rsn:		Drop Count:	
External Treat:	No Treat	Banding Issue:		Pole Load:	0%
Internal Test:	Visual Sound and Bore	GL Shell Avg:	99.00	Wood Strength:	100%
Internal Trt:	No Treat	BG Shell Avg:	99.00	Rmng Strength:	0%
Test Issues:	No Issues	Shell @66:	0.00	Result Status	Pass
Trtmnt Issues:	No Issues	Shell @54:	0.00	Comments:	
Pole Top Cndtn:	Fair	Shell @42:	0.00		
Pole Bttm Cndtn:	Fair	Shell @26:	0.00		
None		Shell @15:	0.00		

SIL_T2_028	2 of 3
------------	--------

Project Status:	CLOSED	Contractor:	UPT		
Foreman:	cglenn001	Current Circ:	33.00	Snow Load:	
Pole Work Status:	Complete	Effective Circ:	33.00	Front Span Length:	
Crew ID:	UPT160	Encl Pkt Count:		Back Span Length:	
Visit Date:	10/09/2012	Exp Pkt Count:		Full Span Count:	
Work Report:	943504	Mch Dmg Count:		Single Span Count:	
Insptn Type:	Test and Treat	Steel Installed:		Equip Count:	

Excavation:	Complete Excavation	No Steel Rsn:		Drop Count:	
External Treat:	BG Treat	Banding Issue:		Pole Load:	0%
Internal Test:	Visual Sound and Pull	GL Shell Avg:	99.00	Wood Strength:	100%
Internal Trt:	Fume	BG Shell Avg:	99.00	Rmng Strength:	0%
Test Issues:	No Issues	Shell @66:	0.00	Result Status	Pass
Trtmnt Issues:	No Issues	Shell @54:	0.00	Comments:	
Pole Top Cndtn:	Fair	Shell @42:	0.00		
Pole Bttm Cndtn:	Fair	Shell @26:	0.00		
None		Shell @15:	0.00		
SIL_T1_062	3 of 3				
Project Status:	CLOSED	Contractor:	DAV		
Foreman:		Current Circ:	33.00	Snow Load:	
Pole Work Status:	Complete	Effective Circ:	33.00	Front Span Length:	
Crew ID:		Encl Pkt Count:		Back Span Length:	
Visit Date:	06/17/2003	Exp Pkt Count:		Full Span Count:	
Work Report:	PO44122	Mch Dmg Count:		Single Span Count:	
Insptn Type:	Test and Treat	Steel Installed:		Equip Count:	
Excavation:	Complete Excavation	No Steel Rsn:		Drop Count:	
External Treat:	BG Treat	Banding Issue:		Pole Load:	0%
Internal Test:		GL Shell Avg:	99.00	Wood Strength:	100%
Internal Trt:	Fume	BG Shell Avg:	0.00	Rmng Strength:	0%
Test Issues:		Shell @66:	0.00	Result Status	Pass
Trtmnt Issues:		Shell @54:	0.00	Comments:	
Pole Top Cndtn:	Fair	Shell @42:	0.00		
Pole Bttm Cndtn:	Fair	Shell @26:	0.00		
		Shell @15:	0.00		